

WI Responsible body name	Standard reference	WI number	Realization date	Standard category	Directive	Directive reference	First OJ offering date registered	Date of Formal Note to EC	Rejected / not rejected	Outcome of the last HAS assessment provided by HAS Consultants before the publication of an EN	other remarks
CEN/TC 153	EN 1673:2020	00153201	2020-12-02	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	rejected	Lack of compliance resolved	REOFFERED The citation of this EN was rejected by the EC in April 2020. CEN solved the EC concerns via the amendment EN ISO 19085-10:2019/A11:2020 (WI 00142203).
CEN/TC 147	EN 13586:2020	00147165	2020-12-16	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant	
CEN/TC 143	EN ISO 16092-4:2020	00143090	2020-09-09	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Compliant	
CEN/TC 274	EN 12312-7:2020	00274090	2020-10-14	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Lack of compliance resolved	
CEN/TC 147	EN 15011:2020	00147150	2020-12-09	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Lack of compliance resolved	
CEN/TC 142	EN ISO 19085-10:2019	00142189	2019-06-05	Main	Machinery (18)	2006/42/EC	2019-07-29	2019-07-31	not rejected	Compliant	
CEN/TC 153	EN 12042:2014+A1:2020	00153215	2020-09-16	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	rejected	Lack of compliance resolved	
CEN/TC 151	EN 15571:2020	00151477	2020-11-18	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant	
CEN/TC 169	EN 1837:2020	00169079	2020-12-02	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Lack of compliance resolved	
CLC/TC 116	EN IEC 62841-2-6:2020	70011	2020-10-09	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant	
CLC/TC 116	EN IEC 62841-2-6:2020/A11:2020	70061	2020-10-09	Amendment	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant	
CEN/TC 196	EN 1804-2:2020	00196036	2020-12-23	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Lack of compliance resolved	
CEN/TC 150	EN 16307-1:2020	00150119	2020-08-26	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Lack of compliance resolved	
CEN/TC 168	EN 12385-3:2020	00168138	2020-12-09	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	rejected	Compliant	
CEN/TC 196	EN 1804-3:2020	00196038	2020-12-23	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Lack of compliance resolved	
CEN/TC 147	EN 12999:2020	00147159	2020-10-14	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant	
CEN/TC 147	EN 13155:2020	00147154	2020-12-16	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	rejected	Compliant	After the offering by CEN the error was discovered by the EC / Member states following which the TC took the decision requesting the EC to <b>not</b> cite the EN

CEN/TC 142	EN ISO 19085-10:2019/A11:2020	00142203	2020-09-16	Amendment	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Compliant
CEN/TC 143	EN ISO 16092-2:2020	00143089	2020-09-09	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Compliant
CEN/TC 150	EN 1175:2020	00150098	2020-07-22	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Lack of compliance resolved
CEN/TC 150	EN 1459-5:2020	00150129	2020-12-23	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Lack of compliance resolved
CEN/TC 12	EN 16808:2020	00012337	2020-08-05	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Compliant
CEN/TC 256	EN 15746-2:2020	00256900	2020-12-23	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	rejected	Lack of compliance resolved
CEN/TC 150	EN 1459-4:2020	00150069	2020-12-23	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	rejected	Lack of compliance resolved
CEN/TC 274	EN 12312-3:2017+A1:2020	00274097	2020-07-29	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Compliant
CEN/TC 153	EN 1974:2020	00153178	2020-11-25	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant
CEN/TC 147	EN 17076:2020	00147135	2020-12-09	Main	Machinery (18)	2006/42/EC	2021-02-26		rejected	Lack of compliance resolved
CEN/TC 196	EN 1804-1:2020	00196037	2020-12-23	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant
CEN/TC 123	EN ISO 11553-1:2020/A11:2020	00123110	2020-11-11	Amendment	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant
CEN/TC 10	EN 81-40:2020	00010125	2020-09-16	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Lack of compliance resolved
CEN/TC 145	EN ISO 20430:2020	00145076	2020-07-01	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Compliant
CEN/TC 151	EN 16564:2020	00151478	2020-11-18	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant
CEN/TC 147	EN 16851:2017+A1:2020	00147176	2020-12-16	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-03-02	not rejected	Compliant
CEN/TC 397	EN 16486:2014+A1:2020	00397005	2020-08-19	Main	Machinery (18)	2006/42/EC	2020-11-03	2020-11-06	not rejected	Lack of compliance resolved
CEN/TC 123	EN ISO 11553-1:2020	00123089	2020-04-15	Main	Machinery (18)	2006/42/EC	2021-02-26	2021-02-03	not rejected	Compliant

This WI was covered by the pilot project on feedback: Consultants provided positive feedback on the changes made by TC to resolve the LoC assessment.

This WI was covered by the pilot project on feedback: Consultants provided positive feedback on the changes made by TC to resolve the LoC assessment.